DIN EN 15622:2010-06 (E)

Copper and copper alloys - Determination of lead content - Flame atomic absorption spectrometric method (FAAS)

Contents

Page

Foreword 3

1 Scope 4

2 Normative references 4

3 Principle 4

4 Reagents 4

5 Apparatus 5

6 Sampling 5

7 Procedure 5
7.1 Preparation of the test portion solution 5
7.1.1 Test portion 5
7.1.2 Test portion solution 5
7.1.3 Lead mass fractions between 0,01 % and 0,15 % 6
7.1.4 Lead mass fractions between 0,1 % and 0,75 % 6
7.1.5 Lead mass fractions between 0,5 % and 5,0 % 6
7.2 Blank test 6
7.3 Check test 6
7.4 Establishment of the calibration curve 6
7.4.1 Preparation of the calibration solutions 6
7.4.2 Adjustment of the atomic absorption spectrometer 8
7.4.3 Spectrometric measurement 8
7.4.4 Calibration curve 8
7.5 Determination 8
7.5.1 General 8
7.5.2 Preliminary spectrometric measurement 9
7.5.3 Spectrometric measurements 9

8 Expression of results 9
8.1 Use of calibration curve 9
8.2 Use of bracketing method 9

9 Precision 10

10 Test report 11

Bibliography 12