ISO 11790:2010-09 (E)

Copper, lead, zinc and nickel concentrates - Guidelines for the inspection of mechanical sampling systems

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 General consideration 2
4.1 Precision 2
4.2 Quality variation 2
4.3 Bias 2
4.4 Operation of the sampling system 3

5 Establishment of inspection system 3
5.1 General 3
5.2 Audits 4
5.3 Mechanical inspections 4
5.4 Operational inspections 4

6 Procedures 4
6.1 Audits 4
6.2 Mechanical inspections 5
6.3 Operational inspections 6
6.4 Control charts 7
6.4.1 General 7
6.4.2 Sampling ratio 7
6.4.3 Extraction ratio 7
6.5 Sampling records 10
6.6 Operator's inspection report 10

Annex A (informative) Example of a sampling checklist for copper ore 11

Annex B (informative) Example of sampling plant operator's inspection report on a shift basis 14

Annex C (informative) Example of sampling-system operations inspection summary 18