DIN EN 15616:2013-02 (E)

Copper and copper alloys - Determination of cadmium content - Flame atomic absorption spectrometric method (FAAS)

Contents

Page

Foreword 3

1 Scope 4

2 Normative references 4

3 Principle 4

4 Reagents 4

5 Apparatus 5

6 Sampling 5

7 Procedure 5

8 Expression of results 8

9 Precision 10

10 Test report 11

Bibliography 12