DIN EN 15024-2:2018-06 (E)

Copper and copper alloys - Determination of zinc content - Part 2: Flame atomic absorption spectrometric method (FAAS)

Contents

Page

European foreword 3

1 Scope 4

2 Normative references 4

3 Principle 4

4 Reagents 4

5 Apparatus 5

6 Sampling 5

7 Procedure 5
7.1 Preparation of the test portion solution 5
7.2 Blank test 6
7.3 Check test 6
7.4 Establishment of the calibration curve 7
7.5 Determination 9

8 Expression of results 10
8.1 Use of the calibration curve 10
8.2 Use of bracketing method 11

9 Precision 11

10 Test report 13

Bibliography 14