DIN EN 14977:2006-09 (E)

Copper and copper alloys - Detection of tensile stress - 5 % ammonia test

Contents

Page

Foreword 3

Introduction 4

1 Scope 5

2 Principle 5

3 Terms and definitions 5

4 Test solution 5

5 Test pieces 6

6 Procedure 6

7 Test requirements 6

8 Test report 6

Bibliography 7