ISO 13292:2006-03 (E)

Copper, lead, zinc and nickel concentrates - Experimental methods for checking the bias of sampling

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 General requirements and recommendations 1

4 Sampling and sample processing methods 2
4.1 Sampling 2
4.1.1 General 2
4.1.2 Checking bias in mechanical sampling 3
4.1.3 Checking difference between sampling at different locations 3
4.2 Sample processing and analysis 3

5 Analysis of experimental data 3
5.1 Statistical basis 3
5.2 Determination of the mean difference and its standard deviation 4
5.3 Determination of the required number of data sets 4
5.4 Statistical test 6

Annex A (informative) Numerical examples of determining the bias of sampling 7

Bibliography 11