DIN EN 15024-2:2007-01 (E)

Copper and copper alloys - Determination of zinc content - Part 2: Flame atomic absorption spectrometry method (FAAS)

Contents

Page

Foreword 3

1 Scope 4

2 Normative references 4

3 Principle 4

4 Reagents and materials 4

5 Apparatus 5

6 Sampling 5

7 Procedure 6

8 Expression of results 11

9 Precision 12

10 Test report 13

Bibliography 14