ISO/TS 13399-311:2016-03 (E)

Cutting tool data representation and exchange - Part 311: Creation and exchange of 3D models - Solid reamers

Contents

Page

Foreword v

Introduction vii

1 Scope 1

2 Normative references 1

3 Starting elements, coordinate systems, planes 2
3.1 General 2
3.2 Reference system 2
3.3 Primary coordinate system and mounting coordinate system 2
3.4 Coordinate system at the cutting part 3
3.5 Planes 4
3.6 Cutting reference point 5

4 Design of the model 5
4.1 General 5
4.2 Necessary properties for the connection interface feature 6

5 Cylindrical reamer 6
5.1 General 6
5.2 Necessary properties 7
5.3 Geometry of the non-cutting part including the connection 7
5.4 Geometry of the cutting part 8
5.5 Complete cylindrical reamer 9

6 Tapered reamer 9
6.1 General 9
6.2 Necessary properties 10
6.3 Geometry of the non-cutting part including the connection 10
6.4 Geometry of the cutting part 10
6.5 Complete tapered reamer 11

7 Stepped reamer 11
7.1 General 11
7.2 Necessary properties 12
7.3 Geometry of the non-cutting part including the connection 13
7.4 Geometry of the cutting part 13
7.5 Complete stepped reamer 14

8 Bell-style reamer 14
8.1 General 14
8.2 Necessary properties 15
8.3 Geometry of the non-cutting part including the connection 16
8.4 Geometry of the cutting part 16
8.5 Complete bell-style reamer 17

9 Shell reamer 17
9.1 General 17
9.2 Necessary properties 18

9.3 Geometry of the non-cutting part including the connection 18
9.4 Geometry of the cutting part 19
9.5 Complete shell reamer 20

10 Design of details 21
10.1 Basics for modelling 21
10.2 Contact/clamping surfaces -- Orientation 21
10.3 Chamfers and roundings 21

11 Attributes of surfaces -- Visualization of the model features 21

12 Structure of the design elements (tree of model) 21

13 Data exchange model 22

Annex A (informative) Information about nominal dimensions 23

Bibliography 24