ISO 6344-2:2021-11 (E)

Coated abrasives - Determination and designation of grain size distribution - Part 2: Macrogrit sizes P12 to P220

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Grain size distribution of macrogrit sizes P12 to P220 1

5 Test method of macrogrit sizes P12 to P220 4
5.1 Macro-P-Mastergrits 4
5.2 Apparatus 4
5.3 Checking of the common use utility test sieves 4
5.4 Preparation 5
5.4.1 Preparation of the test portion 5
5.4.2 Mounting of test sieves 5
5.4.3 Determination of the Macro-P-Mastergrit values for the utility test sieving 5
5.5 Procedure 6
5.6 Evaluation 6

6 Test report 7

7 Designation 8

8 Marking 8

Annex A (informative) Template for recording results of sieving analysis of macrogrit P sizes 9

Annex B (informative) Examples of recording results of sieving analysis of macrogrit P sizes 10