ISO 3002-1:1982-08 (E)

Basic quantities in cutting and grinding; Part 1 : Geometry of the active part of cutting tools; General terms, reference systems, tool and working angles, chip breakers

Contents

Page

1 Scope and field of application 1

2 Reference 1

3 General terms 1
3.1 Surfaces on the workpiece 1
3.2 Tool elements 1
3.3 Tool surfaces 1
3.4 Cutting edges 2
3.5 Dimensions 3
3.6 Tool and workpiece motions 8

4 Reference systems 12
4.1 Tool-in-hand system 12
4.2 Tool-in-use system 19

5 Tool and working angles 26
5.1 Tool angles 26
5.2 Working angles 33
5.3 Sign Convention for angles 38

6 Summary of angles 39

7 Chip breaker 42

Annex : Lists of equivalent terms in French, Russian, German, Italian and Dutch 46