DIN EN 15859:2010-08 (E)

Air Quality - Certification of automated dust arrestment plant monitors for use on stationary sources - P erformance criteria and test procedures

Contents

Page

Foreword 4

0 Introduction 5

1 Scope 7

2 Normative references 7

3 Terms and definitions 7

4 Symbols and abbreviations 12
4.1 Symbols 12
4.2 Abbreviations 13

5 General requirements 14
5.1 Application of performance criteria 14
5.2 Ranges to be tested 14
5.2.1 General 14
5.2.2 Certification range for filter dust monitor 14
5.2.3 Supplementary ranges for filter dust monitors 14
5.2.4 Type of arrestment plant for filter leakage monitors 14
5.2.5 Expression of performance criteria with respect to ranges 15
5.2.6 Ranges of optical in-situ instrument with variable optical length (cross-stack) 15
5.3 Manufacturing consistency and changes to instrument design 15
5.4 Qualifications of test laboratories 15

6 Performance characteristics for laboratory testing 15
6.1 Instrument for testing 15
6.2 CE labelling 15
6.3 Security 16
6.4 Output ranges and zero-point 16
6.5 Additional outputs on filter leakage monitors 16
6.6 Display of operational status signals 16
6.7 Degrees of protection provided by enclosures 16
6.8 Response time 16
6.9 Detection time 16
6.10 Repeatability standard deviation at automatic internal zero point 16
6.11 Repeatability standard deviation at automatic internal reference point 17
6.12 Automatic internal zero and reference point checks 17
6.13 Influence of ambient temperature 17
6.14 Influence of sample gas flow for extractive instrument 17
6.15 Influence of voltage variations 17
6.16 Influence of vibration 17
6.17 Cross-sensitivity 17
6.18 Excursion of measurement beam of cross-stack in situ instruments 18
6.19 Detection limit 18

7 Performance characteristics for field testing 18
7.1 Calibration function for filter dust monitors 18
7.2 Functional test of filter leakage monitor 18
7.2.1 General 18

7.2.2 Plant failure detection test ... 18
7.2.3 Simulated filter failure test ... 19
7.3 Maintenance interval ... 19
7.4 Drift of automatic internal zero point and automatic internal reference point ... 19
7.5 Availability ... 19
7.6 Reproducibility ... 19

8 Performance criteria ... 19

9 General test requirements ... 21

10 Test procedures for laboratory tests ... 22
10.1 Instrument for testing ... 22
10.2 CE labelling ... 22
10.3 Security ... 22
10.4 Output ranges and zero point ... 23
10.5 Additional outputs on filter leakage monitors ... 23
10.6 Display of operational status signals ... 23
10.7 Degrees of protection provided by enclosures ... 23
10.8 Response time ... 23
10.9 Detection time ... 25
10.10 Repeatability standard deviation at automatic internal zero and reference points ... 25
10.11 Influence of ambient temperature ... 25
10.12 Influence of sample gas flow for extractive instruments ... 26
10.13 Influence of voltage variations ... 27
10.14 Influence of vibration ... 28
10.15 Cross-sensitivity ... 29
10.16 Excursion of measurement beam of cross-stack in situ instruments ... 29
10.17 Detection limit ... 29

11 Requirements for field tests ... 30
11.1 Provisions ... 30
11.2 Field test duration ... 30

12 Test procedures for field tests ... 30
12.1 Calibration function for filter dust monitor ... 30
12.2 Functional test of filter leakage monitor ... 31
12.2.1 Plant failure detection test ... 31
12.2.2 Simulated filter failure test ... 31
12.3 Maintenance interval ... 31
12.4 Drift of automatic internal zero point and automatic internal reference point ... 32
12.5 Availability ... 32
12.6 Reproducibility ... 33

13 Test report ... 35

Annex A (informative) Elements of recommended performance testing report ... 36

Bibliography ... 38