ISO 22262-1:2012-07 (E)

Air quality - Bulk materials - Part 1: Sampling and qualitative determination of asbestos in commercial bulk materials

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Termsanddefinitions 1

3 Symbols and abbreviated terms 7

4 Principle 8
4.1 General 8
4.2 Substance determination 8
4.3 Type of sample 8
4.4 Range 8
4.5 Limit of detection 9
4.6 Limitations of PLM in the detection of asbestos 9

5 Sample collection 9
5.1 Requirements 9
5.2 Procedure 10

6 Sample preparation 14
6.1 General 14
6.2 Removal of organic materials by ashing 14
6.3 Removal of soluble constituents by acid treatment 14
6.4 Sedimentationandflotation 14
6.5 Combination of gravimetric reduction procedures 14

7 Analysis by PLM 14
7.1 Requirements 14
7.2 Qualitative analysis by PLM 19

8 Analysis by SEM 29
8.1 General 29
8.2 Requirements 29
8.3 Calibration 29
8.4 Sample preparation 30
8.5 Qualitative analysis by SEM 30

9 Analysis by transmission electron microscope 31
9.1 General 31
9.2 Requirements 32
9.3 Calibration 32
9.4 Sample preparation 33
9.5 Qualitative analysis by TEM 33

10 Test report 35

Annex A (normative) Types of commercial asbestos-containing material 36

Annex B (normative) Interference colour chart 40

Annex C (normative) Dispersion staining charts 41

Annex D (normative)AsbestosidentificationbyPLManddispersionstainingin commercial materials .. 43

Annex E (normative)AsbestosidentificationbySEMincommercialmaterials 52

Annex F (normative)AsbestosidentificationbyTEMincommercialmaterials 58

Annex G (informative) Example of sampling record 67

Annex H (informative) Example of test report 68

Bibliography 69