ISO 10312:2019-10 (E)

Ambient air - Determination of asbestos fibres - Direct transfer transmission electron micros copy method

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Symbols and abbreviated terms 5

5 Type of sample 6

6 Range 6

7 Limit of detection 6

8 Principle 7

9 Reagents 7

10 Apparatus 8
10.1 Air sampling -- Equipment and consumable supplies 8
10.1.1 Filter cassette 8
10.1.2 Sampling pump 8
10.1.3 Stand 8
10.1.4 Personal sampling 8
10.1.5 Flowmeter 8
10.2 Specimen preparation laboratory 9
10.3 Equipment for analysis 9
10.3.1 Transmission electron microscope 9
10.3.2 Energy dispersive X-ray analyser 11
10.3.3 Plasma asher 11
10.3.4 Vacuum coating unit 11
10.3.5 Sputter coater 11
10.3.6 Solvent washer (Jaffe washer) 11
10.3.7 Condensation washer 12
10.3.8 Slide warmer or oven 13
10.3.9 Ultrasonic bath 13
10.3.10 Carbon grating replica 13
10.3.11 Calibration specimen grids for EDXA 13
10.3.12 Carbon rod sharpener 14
10.3.13 Disposable tip micropipettes 14
10.4 Consumable supplies 14
10.4.1 Copper or nickel electron microscope grids 14
10.4.2 Gold or nickel electron microscope grids 14
10.4.3 Carbon rod electrodes 14
10.4.4 Routine electron microscopy tools and supplies 14
10.4.5 Reference asbestos samples 14
10.4.6 Reference samples of mineral fibres other than asbestos 15

11 Air sample collection 15

12 Procedure for analysis 16
12.1 General 16
12.2 Cleaning of sample cassettes 16
12.3 Direct preparation of TEM specimens from polycarbonate filters 17
12.3.1 Selection of filter area for carbon coating 17
12.3.2 Carbon coating of filter portions 17
12.3.3 Preparation of the Jaffe washer 17
12.3.4 Placing of specimens in the Jaffe washer 17

12.4 Direct preparation of TEM specimens from cellulose ester filters 18
12.4.1 Selection of area of filter for preparation 18
12.4.2 Preparation of solution for collapsing cellulose ester filters 18
12.4.3 Filter collapsing procedure 18
12.4.4 Plasma etching of the filter surfaces 18
12.4.5 Carbon coating 18
12.4.6 Preparation of the Jaffe washer 18
12.4.7 Placing of specimens in the Jaffe washer 18
12.5 Criteria for acceptable TEM specimen grids 19
12.6 Procedure for structure counting by TEM 19
12.6.1 General 19
12.6.2 Measurement of mean opening area 20
12.6.3 TEM alignment and calibration procedures 20
12.6.4 Determination of criterion for termination of TEM examination 20
12.6.5 General procedure for structure counting and size analysis 21
12.6.6 Magnification requirements 23
12.7 Blank and quality control determinations 24
12.8 Calculation of results 24

13 Performance characteristics 25
13.1 General 25
13.2 Interferences and limitations of fibre identification 25
13.3 Precision and accuracy 25
13.3.1 Precision 25
13.3.2 Accuracy 26
13.3.3 Inter-laboratory and intra-laboratory analyses 26
13.4 Limit of detection 26

14 Test report 27

Annex A (normative) Determination of operating conditions for plasma asher 30

Annex B (normative) Calibration procedures 31

Annex C (normative) Structure counting criteria 34

Annex D (normative) Fibre identification procedure 44

Annex E (normative) Determination of the concentration of asbestos fibres and bundles longer than 5 µm, and PCM equivalent asbestos fibres 61

Annex F (normative) Calculation of results 62

Annex G (informative) Strategies for collection of air samples 68

Annex H (informative) Methods for removal of gypsum fibres 69

Bibliography 70