DIN EN 1948-1:2006-06 (E)

Stationary source emissions - Determination of the mass concentration of PCDDs/PCDFs and dioxin-like PCBs - Part 1: Sampli ng of PCDDs/PCDFs

Contents

Page

Foreword 3

Introduction 7

1 Scope 8

2 Normative references 8

3 Terms and definitions 9

4 Symbols and abbreviations 11

5 Principle of the complete PCDD/PCDF measurement procedure 12

6 Sampling device and materials 15

7 Minimum requirements for sampling 18

8 Safety measures and transport 21

9 Preparations and sampling 21

Annex A (informative) Toxicity and toxic equivalency 27

Annex B (informative) Examples of operation 30

Annex C (informative) Examples of adsorbents and their preparations and cleaning 58

Annex D (informative) Sampling measurement record 59

Annex E (informative) Relations to EU Directives 62

Bibliography 63