DIN EN ISO 2811-1:2011-06 (E)

Paints and varnishes - Determination of density - Part 1: Pyknometer method (ISO 2811-1:2011)

Contents

Page

Foreword 3

1 **Scope** 4

2 **Normative references** 4

3 **Terms and definitions** 4

4 **Principle** 4

5 **Temperature** 5

6 **Apparatus** 5

7 **Sampling** 5

8 **Procedure** 5
8.1 **General** 5
8.2 **Determination** 6

9 **Calculation** 7

10 **Precision** 7
10.1 **Repeatability limit,** r 7
10.2 **Reproducibility limit,** R 7

11 **Test report** 8

Annex A (informative) **Example of a calibration method** 9

Annex B (informative) **Temperature variation** 11

Bibliography 13