ISO 16474-1:2013-11 (E)

Paints and varnishes - Methods of exposure to laboratory light sources - Part 1: General guidance

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Principle 2
4.1 General 2
4.2 Significance 2
4.3 Use of accelerated tests with laboratory light sources 4

5 Requirements for laboratory exposure devices 4
5.1 Irradiance 4
5.2 Temperature 6
5.3 Humidity and wetting 8
5.4 Other requirements for the exposure device 9

6 Test specimens -- Preparation, replicates, storage and conditioning 9
6.1 Handling of test specimens 9
6.2 Form, shape, preparation 9
6.3 Number of test specimens 10
6.4 Storage and conditioning 10

7 Test conditions and procedure 11
7.1 Set points for exposure conditions 11
7.2 Property measurements on test specimens 11

8 Periods of exposure and evaluation of test results 12
8.1 General 12
8.2 Sampling 12
8.3 Determination of changes in properties after exposure 12
8.4 Use of control materials 12
8.5 Use of results in specifications 12

9 Test report 13

Annex A (informative) Procedure for measuring the irradiance uniformity in the specimen exposure area 15

Annex B (informative)Factorsthatdecreasethedegreeofcorrelationbetweenartificial acceleratedweatheringorartificialacceleratedirradiationexposuresandactual- use exposures 18

Annex C (informative) Solar spectral irradiance standard 21

Bibliography 22