ISO 2811-1:2023-01 (E)

Paints and varnishes - Determination of density - Part 1 : Pycnometer method

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Principle 1

5 Temperature 1

6 Apparatus 2

7 Sampling 3

8 Procedure 3
8.1 General 3
8.2 Determination 4

9 Calculation 4

10 Precision 5
10.1 Repeatability limit, r 5
10.2 Reproducibility limit, R 5

11 Test report 5

Annex A (informative) Example of a calibration method 6

Annex B (normative) Temperature variation 8

Bibliography 10