ISO 19403-2:2024-09 (E)

Paints and varnishes - Wettability - Part 2: Determination of the surface free energy of solid surfaces by measuring the contact angle

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Principle 1

5 Apparatus and materials 2

6 Sampling 3

7 Procedure 3
7.1 General for measuring on the horizontal drop 3
7.1.1 Setting up the contact angle measuring system 3
7.1.2 Test conditions 4
7.1.3 Conditioning of the test panels 4
7.2 Measurement 4
7.2.1 General 4
7.2.2 Static method 4
7.2.3 Dynamic method (progressive contact angle) 5
7.2.4 Determination of the contact angle 6

8 Evaluation 6
8.1 General 6
8.2 Owens-Wendt-Rabel-Kaelble method (OWRK method) 6
8.3 Wu method 7

9 Precision 8
9.1 General 8
9.2 Repeatability limit, r 8
9.3 Reproducibility limit, R 8
9.4 Calculation in accordance with the Owens-Wendt-Rabel-Kaelble method 8

10 Test report 9

Annex A (informative) Notes on measuring practice 10

Bibliography 14