ISO 2808:2007-02 (E)

Paints and varnishes - Determination of film thickness

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Determination of wet-film thickness 3
4.1 General 3
4.2 Mechanical methods 3
4.2.1 Principle 3
4.2.2 Field of application 3
4.2.3 General 3
4.2.4 Method 1A -- Comb gauge 4
4.2.5 Method 1B -- Wheel gauge 5
4.2.6 Method 1C -- Dial gauge 6
4.3 Gravimetric method 7
4.3.1 Principle 7
4.3.2 Field of application 7
4.3.3 General 7
4.3.4 Method 2 -- By difference in mass 7
4.4 Photothermal method 8
4.4.1 Principle 8
4.4.2 Field of application 8
4.4.3 General 9
4.4.4 Method 3 -- Determination using thermal properties 9

5 Determination of dry-film thickness 9
5.1 General 9
5.2 Mechanical methods 9
5.2.1 Principle 9
5.2.2 Field of application 10
5.2.3 General 10
5.2.4 Method 4A -- By difference in thickness 11
5.2.5 Method 4B -- Depth gauging 13
5.2.6 Method 4C -- Surface profile scanning 15
5.3 Gravimetric method 16
5.3.1 Principle 16
5.3.2 Field of application 16
5.3.3 General 16
5.3.4 Method 5 -- By difference in mass 16
5.4 Optical methods 17
5.4.1 Principle 17
5.4.2 Field of application 18
5.4.3 General 18
5.4.4 Method 6A -- Cross-sectioning 19
5.4.5 Method 6B -- Wedge cut 20
5.5 Magnetic methods 20
5.5.1 General 20

5.5.2 Principle 20
5.5.3 Field of application 20
5.5.4 General 21
5.5.5 Method 7A -- Magnetic pull-off gauge 21
5.5.6 Method 7B -- Magnetic-flux gauge 22
5.5.7 Method 7C -- Magnetic-induction gauge 22
5.5.8 Method 7D -- Eddy-current gauge 23
5.6 Radiological method 24
5.6.1 Principle 24
5.6.2 Field of application 24
5.6.3 General 24
5.6.4 Method 8 -- Beta backscatter method 25
5.7 Photothermal method 25
5.7.1 Principle 25
5.7.2 Field of application 26
5.7.3 General 26
5.7.4 Method 9 -- Determination using thermal properties 27
5.8 Acoustic method 27
5.8.1 Principle 27
5.8.2 Field of application 27
5.8.3 General 27
5.8.4 Method 10 -- Ultrasonic thickness gauge 28

6 Determination of thickness of uncured powder layers 28
6.1 General 28
6.2 Gravimetric method 29
6.2.1 Principle 29
6.2.2 Field of application 29
6.2.3 General 29
6.2.4 Method 11 -- By difference in mass 29
6.3 Magnetic methods 29
6.3.1 Principle 29
6.3.2 Field of application 29
6.3.3 General 30
6.3.4 Method 12A -- Magnetic-induction gauge 30
6.3.5 Method 12B -- Eddy-current gauge 31
6.4 Photothermal method 31
6.4.1 Principle 31
6.4.2 Field of application 31
6.4.3 General 31
6.4.4 Method 13 -- Determination using thermal properties 31

7 Measurement of film thickness on rough surfaces 32
7.1 General 32
7.2 Apparatus and materials 33
7.3 Procedure 33
7.3.1 Verification 33
7.3.2 Measurement 33
7.3.3 Number of readings 33

8 Test report 33

Annex A (informative) Overview of methods 35

Bibliography 38