ISO 9276-3:2008-07 (E)

Representation of results of particle size analysis - Part 3: Adjustment of an experimental curve to a reference model

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Symbols and abbreviated terms 2

4 Adjustment of an experimental curve to a reference model 3
4.1 General 3
4.2 Quasilinear regression method 3
4.3 Non-linear regression method 3

5 Goodness of fit, standard deviation of residuals and exploratory data analysis 6

6 Conclusions 7

Annex A (informative) Influence of the model on the regression goodness of fit 9

Annex B (informative) Influence of the type of distribution quantity on the regression result 11

Annex C (informative) Examples for non-linear regression 15

Annex D (informative) 2-Test of number distributions of known sample size 17

Annex E (informative) Weighted quasilinear regression 20

Bibliography 23