# ISO 12828-1:2011-11 (E)

## Validation method for fire gas analysis - Part 1: Limits of detection and quantification

## Contents

Page


Foreword ..... iv

Introduction ..... v

1 Scope ..... 1

2 Normative references ..... 1

3 Terms and definitions ..... 2

4 Symbols ..... 2

5 General considerations ..... 3
5.1 Limit of detection: table of risks ..... 3
5.2 Limit of quantification: effect on repeatability r ..... 3
5.3 Typically accepted values for limits of detection and quantification ..... 4

6 Methods for determining limits of detection and quantification ..... 5
6.1 Principles and summary of methods ..... 5
6.2 Main method 1 - Determination of LD and LQ from matrix data from blank samples ..... 6
6.3 Main method 2 - Determination of LD and LQ from the linearity of calibration data ..... 8
6.4 Main method 3 -- Checking a given or prescribed quantification limit ..... 9
6.5 Other methods ..... 11

7 Presentation of results ..... 11
7.1 Minimum requirements ..... 11
7.2 Reporting results from analyses ..... 12

Annex A (informative) Examples of applications ..... 14

Annex B (informative) Examples of importance of limits of detection and of quantification ..... 18

Bibliography ..... 20