ISO 14934-4:2014-08 (E)

Fire tests - Calibration and use of heat flux meters - Part 4: Guidance on the use of heat flux meters in fire tests

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 General information on heat flux meters 1
4.1 General 1
4.2 Principle of measurement 2
4.3 Design of heat flux meter 3
4.4 Measurement characteristics 5
4.5 Physical shape of heat flux meter 8

5 Attachments to heat flux meters 9
5.1 Air purging 9
5.2 Windows 10
5.3 Cooling system 11

6 Selection of a suitable heat flux meter 12
6.1 General 12
6.2 Range of measurement 12
6.3 Type, dimensions and orientation 13
6.4 View angle 14
6.5 Response time 14
6.6 Sensitivity to convective heat transfer 14

7 Performing a measurement 14
7.1 Installation 14
7.2 Target surface 15
7.3 Electronics 15
7.4 Relationship between output voltage and total heat flux 15

8 Calibration 16
8.1 Secondary standard heat flux meter 16
8.2 Working standard heat flux meters 16
8.3 Frequency of calibration 16

9 Maintenance 16
9.1 Absorber 16
9.2 Wiring 16
9.3 Water supply 16

10 Use of heat flux meters in fire tests 16
10.1 General 16
10.2 Ignitability test: ISO 5657 17
10.3 Spread of flame test: ISO 5658 series 17
10.4 Heat release, smoke production and mass loss: ISO 5660 series and ISO 17554 18

10.5 Full-scale room test for surface products: ISO 9705 and ISO 13784 series 18
10.6 Façade tests: ISO 13785 series 18
10.7 Spread of flame test for floor coverings: ISO 9239 series 18

Bibliography 19