ISO 5660-1:2015-03 (E)

Reaction-to-fire tests - Heat release, smoke production and mass loss rate - Part 1: Heat release rate (cone calorimeter method) and smoke production rate (dynamic measurement)

Contents

Page

Foreword v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Symbols 3

5 Principle 4

6 Apparatus 5
6.1 General 5
6.2 Cone-shaped radiant electrical heater 5
6.3 Radiation shield 5
6.4 Irradiance control 5
6.5 Weighing device 5
6.6 Specimen holder 6
6.7 Retainer frame 6
6.8 Exhaust gas system with flow measuring instrumentation 6
6.9 Gas sampling apparatus 6
6.10 Ignition circuit 7
6.11 Ignition timer 7
6.12 Oxygen analyser 7
6.13 Heat flux meters 7
6.14 Calibration burner 7
6.15 Data collection and analysis system 8
6.16 Optional side screens 8
6.17 Smoke obscuration measuring system 8
6.18 Smoke system thermocouple 8
6.19 Optical filters 8

7 Suitability of a product for testing 9
7.1 Surface characteristics 9
7.2 Asymmetrical products 9
7.3 Materials of short burning time 9
7.4 Composite specimens 9
7.5 Dimensionally unstable materials 9
7.6 Materials that require testing under compression 10

8 Specimen construction and preparation 10
8.1 Specimens 10
8.2 Conditioning of specimens 10
8.3 Preparation 11
8.3.1 Specimen wrapping 11
8.3.2 Specimen preparation 11
8.3.3 Preparing specimens of materials that require testing under compression 11

9 Test environment 11

10 Calibration 12
10.1 Preliminary calibrations 12
10.1.1 General 12
10.1.2 Irradiance control system response characteristics 12
10.1.3 Weighing device response time 12
10.1.4 Weighing device output drift 12
10.1.5 Oxygen analyser delay and response times 12
10.1.6 Oxygen analyser output noise and drift 13
10.1.7 Effect of side screens 13
10.2 Operating calibrations 14

10.2.1 General 14
10.2.2 Weighing device accuracy 14
10.2.3 Oxygen analyser 14
10.2.4 Heat release rate calibration 14
10.2.5 Heater calibration 15
10.3 Smoke meter calibration 15
10.3.1 Calibration with neutral density filters 15
10.3.2 Calibration before test 15
10.4 Less frequent calibrations 15
10.4.1 Operating heat flux meter calibration 15
10.4.2 Linearity of heat release rate measurements 15
10.4.3 Accuracy of calibration burner flow meter 15

11 Test procedure 16
11.1 General precautions 16
11.2 Initial preparation 16
11.3 Procedure 16

12 Calculations 17
12.1 General 17
12.2 Calibration constant for oxygen consumption analysis 18
12.3 Heat release rate 18
12.4 Exhaust duct flow rate 18
12.5 Mass loss rate 19
12.6 Smoke obscuration 19

13 Test report 20

Annex A (informative) Commentary and guidance notes for operators 31

Annex B (informative) Supplementary calculations -- Normalization to the mass loss rate of the specific extinction area of specimen 36

Annex C (informative) Resolution, precision and bias 38

Annex D (informative) Mass loss rate and effective heat of combustion 44

Annex E (informative) Testing in the vertical orientation 45

Annex F (informative) Calibration of the working heat flux meter 48

Annex G (informative) Calculation of heat release with additional gas analysis 49

Annex H (informative) Calculation of Effective Critical Heat Flux for Ignition 53

Bibliography 54