ISO 18674-4:2020 (E)

Geotechnical investigation and testing — Geotechnical monitoring by field instrumentation — Part 4: Measurement of pore water pressure: Piezometers

Contents

Foreword

1 Scope

2 Normative references

3 Terms and definitions

4 Symbols and abbreviated terms

5 Instruments

5.1 General
5.2 Open piezometer systems
5.2.1 General
5.2.2 Types of open piezometer systems
5.2.2.1 General
5.2.2.2 Open standpipe piezometer
5.2.2.3 Monitoring well
5.2.2.4 Casagrande piezometer
5.3 Closed piezometer systems
5.3.1 General
5.3.2 Types of closed piezometer systems
5.3.2.1 General
5.3.2.2 Piezometers with diaphragm pressure transducers
5.3.2.3 Piezometers with pneumatically activated pressure valve
5.3.2.4 Hydraulic twin-tube piezometer
5.4 Absolute versus relative measurements and atmospheric compensation
5.5 Requirements for filters
5.5.1 Filters in open piezometer systems
5.5.2 Filters in closed piezometer systems
5.6 Measuring range and accuracy

6 Installation and measuring procedure

6.1 Installation
6.1.1 General
6.1.2 Installation of open piezometer systems
6.1.3 Installation of closed piezometer systems
6.1.4 Checks before, during and after installation
6.1.4.1 General
6.1.4.2 Checking of open piezometer systems
6.1.4.3 Checking of closed piezometer systems
6.1.5 Maintenance
6.2 Carrying out the measurement
6.2.1 Instrumentation check and calibration
6.2.2 Measurement

7 Data processing and evaluation

8 Reporting

8.1 Installation report
8.2 Monitoring report

Annex A (normative) Measuring and evaluation procedure

A.1 Open piezometers
A.1.1 Measuring procedure
A.1.1.1 Manual measurement
A.1.1.2 Automatic measurement
A.1.2 Evaluation procedure
A.1.2.1 Piezometric level
A.1.2.1.1 Manual measurement
A.1.2.1.2 Automatic measurement
A.1.2.2 Pore water pressure and pressure head
A.2 Closed piezometers
A.2.1 Measuring procedure
A.2.1.1 Manual measurement
A.2.1.2 Automatic measurement
A.2.2 Evaluation procedure
A.2.2.1 Pore water pressure and pressure head
A.2.2.2 Piezometric level

Annex B (informative) Geo-engineering applications

Annex C (informative) Protection of piezometers at the ground level

C.1 General
C.2 Open systems
C.3 Closed systems

Annex D (informative) Response time for pore water pressure measurements

Annex E (normative) Fully grouted piezometer installation

Annex F (normative) Measuring negative pore water pressure (soil suction)

Annex G (informative) Measuring examples

G.1 General
G.2 Open standpipe piezometer
G.3 Closed piezometer: Diaphragm piezometer (VW sensor)
G.4 Closed piezometer: pneumatic piezometer

Page count: 58