DIN EN 12272-3:2026-02 (E)

Surface dressing - Test methods - Part 3: Determination of binder aggregate adhesivity by the Vialit plate shock test method

Contents

Page

European foreword 4

Introduction 5

1 Scope 6

2 Normative references 6

3 Terms and definitions 7

4 Active adhesivity, mechanical adhesion and Vialit emulsion adhesivity 7
4.1 Description 7
4.2 Apparatus 8
4.2.1 Flat steel plates 8
4.2.2 3-pointed supports 8
4.2.3 Steel ball 10
4.2.4 Rubber wheel roller 10
4.2.5 Sprayer 10
4.2.6 Balance 10
4.2.7 Climatic chambers 10
4.2.8 Oven 10
4.2.9 Auxiliary items 11
4.3 Procedure 11
4.3.1 Preparation of the binder 11
4.3.2 Preparation of the chippings 11
4.3.3 Preparation of the plates 12
4.3.4 Chippings spreading 12
4.3.5 Temperatures setting 12
4.3.6 Implementation 13
4.4 Expression of results 13
4.5 Test report 14

5 Wetting temperature (only for anhydrous binders) 14
5.1 Description 14
5.2 Apparatus 14
5.3 Procedure 14
5.3.1 Preparation of the binder 14
5.3.2 Preparation of the chippings 15
5.3.3 Preparation of the plates 15
5.3.4 Chippings spreading and rolling 15
5.3.5 Temperatures setting 15
5.3.6 Implementation 15
5.4 Expression of results 15
5.5 Test report 15

6 Fragility temperature (only for anhydrous binders) 15
6.1 Description 15
6.2 Apparatus 15
6.3 Procedure 16
6.3.1 Preparation of the binder 16
6.3.2 Preparation of the chippings 16

6.3.3 Preparation of the plates 16
6.3.4 Spreading and rolling (hot bituminous binders) 16
6.3.5 Temperature setting 16
6.3.6 Implementation 16
6.4 Expression of results 16
6.5 Test report 16

7 Test report 16

Annex A (informative) Summary of the preparation of the plates before testing 18

Annex B (informative) Tables of results 21

Annex C (informative) Measures of the fragility temperature 23

Annex D (informative) Purpose of the Vialit plate shock test 24

Bibliography 25