ISO/TS 14934-4:2007-02 (E)

Fire tests - Calibration of heat flux meters - Part 4: Guidance on the use of heat flux meters in fire tests

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 General information on heat flux meters 1
4.1 General 1
4.2 Principle of measurement 2
4.3 Design of heat flux meter 3
4.4 Measurement characteristics 5
4.5 Physical shape of heat flux meter 7

5 Attachments to heat flux meters 8
5.1 Air purging 8
5.2 Windows 9
5.3 Cooling system 10

6 Selection of a suitable heat flux meter 12
6.1 General 12
6.2 Range of measurement 12
6.3 Type, dimensions and orientation 13
6.4 View angle 13
6.5 Response time 13
6.6 Sensitivity to convective heat transfer 13

7 Performing a measurement 14
7.1 Installation 14
7.2 Target surface 15
7.3 Electronics 15
7.4 Relationship between output voltage and total heat flux 15

8 Calibration 16
8.1 Secondary standard heat flux meter 16
8.2 Working standard heat flux meters 16
8.3 Frequency of calibration 16

9 Maintenance 17
9.1 Absorber 17
9.2 Wiring 17
9.3 Water supply 17

10 Use of heat flux meters in fire tests 17
10.1 General 17
10.2 Ignitability test (see ISO 5657) 17
10.3 Spread of flame test (see ISO 5658, all parts) 17
10.4 Heat release, smoke production and mass loss (see ISO 5658, all parts, and ISO 17554) 18

10.5 Full-scale room test for surface products (see ISO 9705) 18
10.6 Façade tests (see ISO 13785-2) 18
10.7 Spread of flame test for floor coverings (see ISO 9239, all parts) 18
10.8 Intermediate-scale heat-release calorimeter (ICAL) (see ISO/TR 14696) 18

Bibliography 19