ISO 13732-1:2006-09 (E)

Ergonomics of the thermal environment - Methods for the assessment of human responses to contact with surfaces - Part 1: Hot surfa ces

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 2

3 Terms and definitions 2

4 Burn thresholds 3
4.1 General 3
4.2 Burn threshold data 4

5 Assessment of risk of burning 10
5.1 Procedure 10
5.2 Identification of hot, touchable surfaces 10
5.3 Task analysis 11
5.4 Measurements of surface temperatures 11
5.5 Choice of applicable burn threshold value 12
5.6 Comparison of surface temperature and burn threshold 13
5.7 Determination of risk of burning 14
5.8 Repetition 14

6 Protective measures 15
6.1 General 15
6.2 No risk of burning 15
6.3 Risk of burning 15

7 Guidance for setting surface temperature limit values 16
7.1 Procedure 16
7.2 Assessment of risk of burning 16
7.3 Decision upon protective measures 16
7.4 Selection of appropriate values 16
7.5 Setting of surface temperature limit value 17

Annex A (informative) Scientific background 18

Annex B (normative) Contact periods 20

Annex D (informative) Thermal properties of selected materials 23

Annex E (informative) Examples of protective measures against burns 24

Annex F (informative) Example for assessment of risk of burning 26

Annex G (informative) Examples for setting surface temperature limit values 31

Annex H (informative) Safety signs for hot surfaces 35

Bibliography 37