DIN ISO 11421:2010-10 (E)

Optics and optical instruments - Accuracy of optical transfer function (OTF) measurement (ISO 11421:1997)

Contents

Page

National foreword 3

National Annex NA (informative) Bibliography 3

Introduction 4

1 Scope 5

2 Normative reference 5

3 Definitions and symbols 5

4 Sources of inaccuracy in measuring equipment 7

5 Methods of assessing levels of accuracy 14

6 Calculation of overall accuracy of a measurement 22

7 Specifying a general equipment accuracy 23

8 Routine performance evaluation 26

Annex A (normative) Accuracy of PTF measurement 28

Annex B (informative) Determination of rate of change of MTF various parameters 29

Annex C (informative) Example calculation of NAV 31

Annex D (informative) Bibliography 34