ISO 9022-8:2015-03 (E)

Optics and photonics - Environmental test methods - Part 8: High internal pressure, low internal pressure, immersion

Contents

Page

Foreword ... **iv**

Introduction ... **vi**

1 Scope ... **1**

2 Normative references ... **1**

3 General information and test conditions ... **1**

4 Conditioning ... **1**

4.1 Conditioning method 80: High internal pressure ... 1

4.2 Conditioning method 81: Low internal pressure ... 1

4.3 Conditioning method 82: Immersion ... 2

5 Procedure ... **2**

5.1 General ... 2

5.2 Conditioning method 82: Preconditioning of specimen and initial test ... 2

5.3 Conditioning methods 80 and 81: Pressure change curve ... 2

5.4 State of operation 2 ... 3

5.5 Conditioning method 82: Recovery and final test ... 3

5.6 Conditioning method 82: Evaluation ... 3

6 Environmental test code ... **3**

7 Specification ... **3**

Annex A (informative) **Explanatory notes** ... **5**