ISO 9022-12:2015-04 (E)

Optics and photonics - Environmental test methods - Part 12: Contamination

Contents

Page

Foreword iv

Introduction vi

1 Scope 1

2 Normative references 1

3 General information and test conditions 1
3.1 Specimen 1
3.2 Test pad 2
3.3 Test weight and arrangement of test pads 3

4 Conditioning 4
4.1 General 4
4.2 Conditioning method 86: Basic cosmetic substances and artificial hand sweat 4
4.3 Conditioning method 87: Laboratory agents 4
4.4 Conditioning method 88: Production plant resources 4
4.5 Conditioning method 89: Fuels and resources for aircraft, naval vessels, and land vehicles 4

5 Procedure 7
5.1 General 7
5.2 Preconditioning 7
5.3 Test sequence 8
5.4 Recovery 8
5.5 Evaluation 8
5.6 General level for acceptance 8

6 Environmental test code 9

7 Specification 9

Annex A (normative) Determination of pH value of aqueous extract of pad materials 10