DIN EN 16128:2016-02 (E)

Ophthalmic optics - Reference method for the testing of spectacle frames and sunglasses for nickel release

Contents

Page

European foreword 4

Introduction 6

1 Scope 7

2 Normative references 7

3 Terms and definitions 7

4 Principle 8

5 Selection of test samples 8

6 Simulation of wear and corrosion 9
6.1 Preparation of test samples 9
6.2 Procedure 10

7 Coating test 10
7.1 General 10
7.2 Apparatus and consumables 10
7.3 Preparation of test samples for the coating test 11
7.3.1 Parts to be tested 11
7.3.2 Dismantling and/or cutting and/or masking 11
7.3.3 Determination of test area 13
7.3.4 Preparation of electrical contact area 13
7.4 Preparation of saline solution 13
7.5 Procedure 13
7.5.1 Preparation of the electro-chemical cell 13
7.5.2 Insertion and connection of the test part in the electro-chemical cell 14
7.5.3 Determination of open circuit potential and measurement of electrochemical impedance of test samples 14
7.5.4 Calibration and verification of the equipment 15
7.6 Calculation of results 15
7.6.1 General 15
7.6.2 Criteria for pass or fail of the test sample 15
7.7 Test report 15

8 Release of nickel and its quantitative analytical detection (migration test) 16
8.1 General 16
8.2 Apparatus and consumables 16
8.3 Preparation of test samples for the migration test 18
8.3.1 Parts to be tested 18
8.3.2 Guidance on selection of test areas on the parts to be tested 18
8.3.3 Dismantling and degreasing 19
8.4 Procedure 19
8.4.1 Preparation of test paper including determination of its area 19
8.4.2 Preparation of artificial sweat solution 20
8.4.3 Applying artificial sweat solution to the test paper and attaching it to the test sample 21
8.4.4 Blank sample 22
8.4.5 Incubation of test sample with test paper attached (release of nickel into paper) 22

8.4.6 Retrieval of the test paper from the test samples 22
8.4.7 Analysis of the test papers for nickel 22
8.5 Calculation of migration test results 24
8.6 Interpretation of migration test results 25
8.6.1 General 25
8.6.2 Assessment of compliance 25
8.7 Test report 25

Annex A (informative) Cutting and masking of test samples (Coating test) 27

A.1 Fronts 27
A.2 Sides (temples) 28

Annex B (normative) Selection of test areas and application of the test paper (Migration test) 29

B.1 General 29
B.2 Rims 29
B.3 Bridge 30
B.4 Brace bar 31
B.5 Sides 32
B.6 Trims 34

Bibliography 35