ISO 9211-4:2022-03 (E)

Optics and photonics - Optical coatings - Part 4: Specific test methods: abrasion, adhesion and resistance to water

Contents

Page

Foreword ... iv

1 Scope ... 1

2 Normative references ... 1

3 Terms and definitions ... 1

4 Preparation prior to testing ... 1

5 Abrasion tests: cheesecloth/eraser test (conditioning method 01) ... 2
- 5.1 General ... 2
- 5.2 Test conditions ... 2
  - 5.2.1 General ... 2
  - 5.2.2 Moderate abrasion test ... 2
  - 5.2.3 Severe abrasion test ... 2
- 5.3 Degree of severity: abrasion – cheesecloth/eraser test (conditioning method 01) ... 2
- 5.4 Recovery ... 3
- 5.5 Evaluation ... 3

6 Adhesion test: tape test (conditioning method 02) ... 3
- 6.1 General ... 3
- 6.2 Test conditions ... 3
- 6.3 Degree of severity: adhesion – tape test (conditioning method 02) ... 3
- 6.4 Recovery ... 4
- 6.5 Evaluation ... 4

7 Adhesion test: crosshatch test (conditioning method 03) ... 4
- 7.1 General ... 4
- 7.2 Test conditions ... 4
- 7.3 Degree of severity ... 4
- 7.4 Conditioning ... 4
- 7.5 Recovery ... 5
- 7.6 Evaluation ... 5

8 Resistance to water: exposure to water (conditioning method 04) ... 5
- 8.1 General ... 5
- 8.2 Test conditions ... 5
- 8.3 Degree of severity: resistance to water – exposure to water (conditioning method 04) ... 6
- 8.4 Recovery ... 6
- 8.5 Evaluation ... 6

9 Adhesion test: pull-off test (conditioning method 05) ... 7
- 9.1 General ... 7
- 9.2 Test conditions ... 7
- 9.3 Degree of severity: adhesion – pull-of test (conditioning method 05) ... 8
- 9.4 Evaluation ... 8

10 Environmental test code ... 8

Annex A (normative) **Materials for abrasion testing of optical coatings** ... 9

Annex B (informative) **Cheesecloth pad, pad cover and fixture preparation for moderate abrasion testing of optical coatings** ... 12

Annex C (normative) **Visual examination of optical coatings** ... 14

Bibliography ... 15