ISO 23701:2023-04 (E)

Optics and photonics - Laser and laser-related equipment - Photothermal technique for absorption measurement and mapping of optical laser components

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Symbols used and units of measure 2

5 Test method 2
5.1 Test principle 2
5.1.1 General 2
5.1.2 Photothermal lensing (TL) 3
5.1.3 Photothermal deflection (PTD) 3
5.1.4 Rules for selecting reflected and transmitted photothermal detection schemes 3
5.2 Measurement arrangement and test equipment 3
5.2.1 Photothermal detection arrangement 3
5.2.2 Pump laser 6
5.2.3 Probe laser 6
5.2.4 Translation stage 6
5.2.5 Detection unit 7
5.2.6 Data acquisition and processing 7
5.2.7 Environment 7
5.3 Preparation of test sample 7

6 Test procedure 7
6.1 General 7
6.2 Measurements of photothermal amplitude and phase 8
6.3 Maps of photothermal amplitude and phase 8
6.4 Calibration of photothermal amplitude 9
6.5 Assessments of the measurement 10

7 Evaluation 11
7.1 Determination of absorption via photothermal measurement 11
7.2 Determination of absorptance via photothermal calibration 12
7.3 Two-dimensional/three-dimensional maps of absorption 13
7.4 Mapping area and spatial resolution 13

8 Test report 14

Annex A (informative) Theoretical and practical considerations on calibration 16

Annex B (informative) Separation of surface absorption and bulk absorption 18

Annex C (informative) Test report 21

Bibliography 22