ISO 24013:2023-06 (E)

Optics and photonics - Lasers and laser-related equipment - Measurement of phase retardation of optical components for polarized laser radiation

Contents

Page

Foreword ..... **iv**

Introduction ..... **v**

1 Scope **1**

2 Normative references **1**

3 Terms and definitions **1**

4 Symbols and abbreviated terms **1**

5 Measurement principle **2**

6 Preparation of test sample and measuring arrangement **3**
6.1 General 3
6.2 Laser beam preparation 3
6.3 Sample adjustment and system calibration 3
6.3.1 Reflective samples 3
6.3.2 Possible alignment procedure 4
6.3.3 Transmissive samples 4
6.4 Detection system 4
6.4.1 General 4
6.4.2 Polarization analyser 4
6.4.3 Power detector 4

7 Test procedure **5**
7.1 Test procedure for zero or π phase retardation 5
7.1.1 General 5
7.1.2 Simple test procedure for zero absorptance difference 5
7.1.3 Test procedure for non zero absorptance difference 5
7.2 Test procedure for π/2 phase retardation 5
7.2.1 General 5
7.2.2 Simple test procedure for zero absorptance difference 5
7.2.3 Test procedure for non zero absorptance difference 5

8 Evaluation **6**
8.1 General 6
8.2 Evaluation for zero phase retardation 6
8.2.1 Evaluation for zero absorptance difference 6
8.2.2 Evaluation for non-zero absorptance difference 6
8.3 Evaluation for π/2 phase retardation 6
8.3.1 Evaluation for zero absorptance difference 6
8.3.2 Evaluation for non-zero absorptance difference 6

9 Test report **6**

Annex A (informative) **Theoretical background** **8**

Bibliography **16**