ISO/TS 6838:2024-07 (E)

Ophthalmic optics - Contact lenses - Tolerances and methods for measurement of multifocal contact lens addition power

Contents

Page

Foreword ..... **iv**

1 Scope **1**

2 Normative references **1**

3 Terms and definitions **1**

4 Tolerances **2**
4.1 Tolerance limits 2
4.2 Conditioning of contact lenses prior to testing 2
4.3 Tolerances for rigid and soft contact lenses 3

5 Methods of measurement for multifocal add power **3**
5.1 General 3
5.2 Wavefront sensor 3
5.2.1 Wavefront instrument specification 3
5.2.2 Wavefront calibration 3
5.2.3 Wavefront method of measurement 4
5.2.4 Power profile examples 4
5.2.5 Bifocal contact lens 6
5.3 Focimeter 7
5.3.1 Principle 7
5.3.2 Focimeter specification 8
5.3.3 Focimeter calibration 9
5.3.4 Measurement of most plus and least plus power 9

6 Ring test results **10**
6.1 Ring test objectives 10
6.2 Ring test background 10
6.3 Ring test executive summary 11
6.3.1 WFS calibration verification using (13) certified low-power glass lenses 11
6.3.2 Focimeter calibration verification using (10) standard B+L calibration lenses 12
6.3.3 WFS gauge repeatability and reproducibility (GR&R) using PV2 MF HA lenses 12
6.3.4 Focimeter gauge repeatability and reproducibility (GR&R) using PV2 MF HA lenses 12
6.4 Calibration lens accuracy requirements 12
6.4.1 Focimeters 13
6.4.2 Wavefront sensor low-power lenses 13

7 Discussion **15**
7.1 Ring test conclusions 15
7.2 Ring test recommendations 15
7.3 Multifocal add-power measurement challenges 15
7.3.1 Immersed wavefront sensor measurement challenges 15
7.3.2 In-air wavefront sensor measurement challenges 18
7.4 Questions to answer before the TS moves to become a standard 18

Bibliography **20**