ISO 14999-4:2026-05 (E)

Optics and photonics - Measurement of optical elements and optical systems - Part 4: Interpretation and evaluation of surface form and wavefront deformation tolerances specified in ISO 10110

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1
3.1 Mathematical definitions 2
3.2 Definition of optical functions 2
3.3 Definition of Zernike polynomials 6
3.4 Definitions of functions and terms for tolerancing the slope and curvature deviation 6
3.5 Definitions of functions and terms for tolerancing the Zernike residual RMS 9

4 Decomposition of measured data 9

5 Relating interferometric measurements to surface form deviation or transmitted wavefront deformation 12
5.1 Test areas 12
5.2 Quantities 12
5.3 Single-pass transmitted wavefront deformation 12
5.4 Double-pass transmitted wavefront deformation for straight transmission measurements 12
5.5 Surface form deviation 12
5.6 Conversion to other wavelengths 12
5.7 Conversion of non-interferometric measurements to wavefront deformation 13

6 Representation of the measured wavefront deviation as Zernike coefficients 13

7 Measurement and tolerancing of the slope and curvature deviation 13
7.1 General 13
7.2 Quantities 14
7.3 One-dimensional measurement of the slope and curvature deviation 14
7.4 Two-dimensional measurement of the slope and curvature deviation 16
7.5 Detrending 17

8 Calculation procedure for the Zernike residual RMS 17

Annex A (normative) Estimation of peak-to-valley value (PV) 18

Annex B (normative) Zernike polynomials 22

Annex C (normative) Visual interferogram analysis 25

Bibliography 33