ISO 11137-3:2017-06 (E)

Sterilization of health care products - Radiation - Part 3: Guidance on dosimetric aspects of develop ment, validation and routine control

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Terms,definitionsandsymbols 1
3.1 General 1
3.2 Symbols 3

4 Measurement of dose 4
4.1 General 4
4.1.1 Direct and indirect dose measurements 4
4.1.2 Dosimetry systems 4
4.1.3 Best estimate of dose 4
4.2 Dosimetry system selection and calibration 5
4.2.1 General 5
4.2.2 Selection of dosimetry systems 5
4.2.3 Calibration of dosimetry systems 5
4.3 Dose measurement uncertainty 6
4.3.1 General concepts 6
4.3.2 The Guide to the expression of uncertainty in measurement (GUM) methodology 6
4.3.3 Radiation sterilization specific aspects of dose measurement uncertainty 7

5 Establishingthemaximumacceptabledose 8

6 Establishingthesterilizationdose 9

7 Installationqualification 10

8 Operationalqualification 11
8.1 General 11
8.2 Gamma irradiators 11
8.3 Electron beam irradiators 13
8.4 X-ray irradiators 15

9 Performancequalification 17
9.1 General 17
9.2 Gamma irradiators 18
9.2.1 Loading pattern 18
9.2.2 Dosimetry 19
9.2.3 Analysis of dose mapping data 20
9.3 Electron beam irradiators 20
9.3.1 Loading pattern 20
9.3.2 Dosimetry 22
9.3.3 Analysis of dose mapping data 23
9.4 X-ray irradiators 23
9.4.1 Loading pattern 23
9.4.2 Dosimetry 24

9.4.3 Analysis of dose mapping data 25

10 Routinemonitoringandcontrol 25
10.1 General 25
10.2 Frequency of dose measurements 26

AnnexA(informative)Mathematicalmodelling 27

AnnexB(informative)Tablesofreferencesfordosimetry-relatedtestingduringIQ/OQ/PQ 30

AnnexC(informative)Tolerancesassociatedwithdosesusedinsterilizationdosesetting/ substantiationinISO11137-2andISO/TS13004 33

AnnexD(informative)Applicationofdosemeasurementuncertaintyinsettingprocess targetdoses 34

Bibliography 40