ISO 28927-2:2009-12 (E)

Hand-held portable power tools - Test methods for evaluation of vibration emission - Part 2: Wrenches, nut runners and screwdrivers

Contents

Page

Foreword iv

Introduction vi

1 Scope 1

2 Normative references 1

3 Terms, definitions and symbols 2
3.1 Terms and definitions 2
3.2 Symbols 3

4 Basic standards and vibration test codes 3

5 Description of the family of machines 3

6 Characterization of vibration 7
6.1 Direction of measurement 7
6.2 Location of measurements 7
6.3 Magnitude of vibration 13
6.4 Combination of vibration directions 13

7 Instrumentation requirements 13
7.1 General 13
7.2 Mounting of transducers 13
7.3 Frequency weighting filter 13
7.4 Integration time 13
7.5 Auxiliary equipment 14
7.6 Calibration 14

8 Testing and operating conditions of the machinery 14
8.1 General 14
8.2 Operating conditions 15
8.3 Other quantities to be specified 15
8.4 Attached equipment, work piece and task 15
8.5 Operators 18

9 Measurement procedure and validity 19
9.1 Reported vibration values 19
9.2 Declaration and verification of the vibration emission value 19

10 Measurement report 20

Annex A (informative) Model test report for vibration emission of wrenches, nutrunners and screwdrivers 21

Annex B (normative) Determination of uncertainty 23

Annex C (normative) Brake devices -- Assembly drawings and specification of parts 26

Bibliography 39