ISO 16063-21:2003-08 (E)

Methods for the calibration of vibration and shock transducers - Part 21: Vibration calibration by comparison with a reference transducer

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Uncertainty of measurement 2

4 Requirements for apparatus and environmental conditions 3
4.1 General 3
4.2 Environmental conditions 3
4.3 Reference transducer 3
4.4 Vibration generation equipment 4
4.5 Voltage measuring instrumentation 6
4.6 Distortion measuring instrumentation 6
4.7 Oscilloscope 7
4.8 Phase shift measuring instrumentation 7

5 Calibration 7
5.1 Preferred amplitudes and frequencies 7
5.2 Measurement requirements 7
5.3 Calibration procedure 8

6 Expression of results 8

7 Reporting the calibration results 9

Annex A (normative) Expression of uncertainty of measurement in calibration 11

Annex B (normative) Definitions of amplitude sign and phase shift between mechanical motion and vibration transducer electrical output 20

Annex C (informative) Nomogram for conversion between acceleration, velocity and displacement 22

Annex D (informative) Example of uncertainty calculation 24

Bibliography 29