ISO 11161:2007-05 (E)

Safety of machinery - Integrated manufacturing systems - Basic requirements

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Terms and definitions 2

4 Strategy for risk assessment and risk reduction 6
4.1 General 6
4.2 Specification of the limits of the IMS 6
4.3 Determination of the task 6
4.4 Identifying hazardous situations 8
4.5 Risk estimation and risk evaluation 8
4.6 Risk reduction 8

5 Risk assessment 10
5.1 Specifications of the IMS 10
5.2 Identification of hazards and hazardous situations 12
5.3 Risk estimation 13
5.4 Risk evaluation 14

6 Risk reduction 14
6.1 Protective measures 14
6.2 Validation of the protective measures 14

7 Task zone(s) 14
7.1 General 14
7.2 Determination 15
7.3 Design 15
7.4 Functional analysis 16

8 Safeguarding and span of control 16
8.1 Safeguarding of task zones 16
8.2 Span of control 17
8.3 Electrical equipment requirements 17
8.4 Modes 17
8.5 Safeguards 18
8.6 Protective measures when safeguards are suspended 18
8.7 Muting and blanking 20
8.8 Control 20
8.9 Reset of perimeter safeguarding devices 21
8.10 Start/restart 21
8.11 Emergency stop 22
8.12 Measures for the escape and rescue of trapped persons 22

9 Information for use 22
9.1 General 22
9.2 Marking 23

10 Validation of the design 23
10.1 Validation that the design meets the requirements 23
10.2 Validation of the protective measures 23

Annex A (informative) Examples of integrated manufacturing systems (IMSs) 24

Annex B (informative) Flow of information between the integrator, user and suppliers 27

Annex C (informative) Span of control examples within an IMS 28

Annex D (informative) Temporary observation of the automatic process 32

Bibliography 36