ISO 9244:2008-06 (E)

Earth-moving machinery - Machine safety labels - General principles

Contents

Page

Foreword viii

Introduction ix

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Machine safety labels -- Application, presentation and general requirements 4
4.1 Objectives 4
4.2 Location 4
4.3 Effective use 4
4.4 Operator's manuals 4
4.5 Formats 4
4.6 Hazard severity panel 7
4.7 Pictorials 7
4.8 Text in supplementary safety panel 9
4.9 Languages, translations and multi-language machine safety labels 9

5 Colours 10
5.1 Colour specifications 10
5.2 Hazard severity panels 11
5.3 Pictorials and safety signs 11
5.4 Supplementary safety information panels 11
5.5 Borders and panel separation lines 12

6 Dimensions 12

7 Examples of machine safety labels 16
7.1 With text 16
7.2 Without text 16

8 Graphical design of hazard pictorials 16

Annex A (informative) Examples of hazard description pictorials 17

Annex B (informative) Examples of hazard avoidance pictorials 30

Annex C (informative) Examples of machine safety labels without text 37

Annex D (informative) Principles and guidelines for graphic design of hazard and avoidance pictorials 55

Bibliography 71

Figure 1 -- Two-panel combination machine safety label -- With signal word 5

Figure 2 -- Three-panel combination machine safety label -- With signal word 6

Figure 3 -- Two-panel combination machine safety label -- Without signal word 6

Figure 4 -- Meaning of hazard severity panels 7

Figure 5 -- General prohibition sign 8

Figure 6 -- STOP instruction 8

Figure 7 -- Combined pictorial in single panel 8

Figure 8 -- Safety shape for warning signs 9

Figure 9 -- General warning sign 9

Figure 10 -- Machine safety label without text -- Read operator's manual 10

Figure 11 -- Safety sign borders 12

Figure 12 -- Recommended dimensions -- Two-panel format 13

Figure 13 -- Recommended dimensions -- Three-panel format 14

Figure 14 -- Recommended dimensions -- Two-panel format 15

Figure A.1 -- Poisonous fumes or toxic gases -- Asphyxiation 17

Figure A.2 -- Electrical shock/electrocution -- General 17

Figure A.3 -- Electrical shock/electrocution -- Hand 18

Figure A.4 -- Electrical shock/electrocution -- Body 18

Figure A.5 -- Electrical shock/electrocution -- Loader 18

Figure A.6 -- Electrical shock/electrocution -- Excavator 18

Figure A.7 -- Fall from high place 19

Figure A.8 -- Fall from raised loader bucket 19

Figure A.9 -- High pressure fluid -- Injection into flesh 19

Figure A.10 -- High pressure spray -- Erosion of flesh 20

Figure A.11 -- Hot surface -- Burn to finger or hand 20

Figure A.12 -- Hot fluid under pressure 20

Figure A.13 -- Crushing of whole body -- Force applied from above 21

Figure A.14 -- Crushing of whole body -- Force applied from behind 21

Figure A.15 -- Crushing of whole body -- Force applied from side 21

Figure A.16 -- Crushing of whole body -- Bidirectional force applied 21

Figure A.17 -- Crushing of whole body -- Loader bucket or lift arm 22

Figure A.18 -- Crushing of whole body -- Single directional pinned 22

Figure A.19 -- Crushing of whole body -- Excavator 22

Figure A.20 -- Crushing of foot 22

Figure A.21 -- Crushing of fingers or hand -- Force applied from side 23

Figure A.22 -- Crushing of fingers or hand -- Force applied from above 23

Figure A.23 -- Severing of fingers or hand -- Impeller blade 23

Figure A.24 -- Severing of fingers or hand -- Engine fan 23

Figure A.25 -- Severing of fingers or hand -- Sharp object 24

Figure A.26 -- Severing of foot 24

Figure A.27 -- Severing of leg 24

Figure A.28 -- Severing of head -- Tool on rotating shaft 24

Figure A.29 -- Hand and arm entanglement -- Chain or toothed belt drive 25

Figure A.30 -- Hand and arm entanglement -- Belt drive 25

Figure A.31 -- Hand and arm entanglement -- Rotating gears 25

Figure A.32 -- Hand and arm entanglement -- Machinery 25

Figure A.33 -- Hand and arm entanglement -- Auger 26

Figure A.34 -- Leg or foot entanglement -- Auger 26

Figure A.35 -- Full body entanglement -- Machinery 26

Figure A.36 -- Leg or foot entanglement or severing -- Trencher 26

Figure A.37 -- Thrown or flying objects -- Face exposure 27

Figure A.38 -- Thrown or flying objects -- Full body exposure 27

Figure A.39 -- Run-over 27

Figure A.40 -- Machine rollover -- Crush 28

Figure A.41 -- Machine tip-over -- Overload -- Backhoe loader 28

Figure A.42 -- Machine tip-over -- Overload -- Skid steer loader 28

Figure A.43 -- Explosion (used, for example, with starter fluid) 29

Figure A.44 -- Explosion of battery 29

Figure A.45 -- Explosion of battery -- Jump start 29

Figure B.1 -- Read operator's manual 30

Figure B.2 -- Read technical manual for proper service procedures 30

Figure B.3 -- Stay safe distance from hazard -- General 30

Figure B.4 -- Stay safe distance from raised loader lift arm and bucket 31

Figure B.5 -- Stay safe distance from electrical power lines 31

Figure B.6 -- Stay safe distance from articulation area 31

Figure B.7 -- Keep hands safe distance from hazard 31

Figure B.8 -- Secure lifting cylinder with locking device before entering hazardous area 32

Figure B.9 -- Attach support before entering hazardous area 32

Figure B.10 -- Secure locking device before entering hazardous area. Read operator's manual 32

Figure B.11 -- Insert safety lock before entering hazardous area 32

Figure B.12 -- Wait until all machine components have completely stopped before touching them .. 33

Figure B.13 -- Do not jump start the engine 33

Figure B.14 -- Shut off engine and remove key before performing maintenance or repair work 33

Figure B.15 -- Do not ride on fender 34

Figure B.16 -- Do not reach into crushing area 34

Figure B.17 -- Do not stand under bucket 34

Figure B.18 -- Do not loosen cap until cool 35

Figure B.19 -- Do not step 35

Figure B.20 -- No hands 35

Figure B.21 -- No feet 35

Figure B.22 -- No ether -- Low temperature starting aid 36

Figure B.23 -- Eye protection required 36

Figure B.24 -- Face protection required 36

Figure B.25 -- Wear seat belt 36

Figure C.1 -- Stay safe distance from hazard -- General 37

Figure C.2 -- Crushing of whole body -- Stay safe distance from raised loader lift arm and bucket ... 38

Figure C.3 -- Crushing of whole body -- Stay safe distance from articulation area 38

Figure C.4 -- Crushing or pinning of whole body -- Stay safe distance from hazard 39

Figure C.5 -- Crushing of whole body -- Stay safe distance from hazard 39

Figure C.6 -- Thrown or flying objects -- Stay safe distance from hazard 40

Figure C.7 -- Crushing of whole body -- Secure lift cylinder with locking device before entering hazardous area 40

Figure C.8 -- Crushing of whole body -- Attach support before entering hazardous area 41

Figure C.9 -- Crushing of whole body -- Insert safety lock before entering hazardous area 41

Figure C.10 -- Crushing of whole body -- Secure locking device before entering hazardous area -- Read operator's manual 42

Figure C.11 -- Crushing hazard -- Run-over -- Do not jump start engine 42

Figure C.12 -- General safety alert -- Shut off engine and remove key before performing maintenance or repair work 43

Figure C.13 -- Electrical shock or electrocution -- Stay safe distance from electrical power lines 43

Figure C.14 -- Electrical shock or electrocution -- Stay safe distance from electrical power source 44

Figure C.15 -- Electrical shock or electrocution -- Keep hands safe distance from electrical power source 44

Figure C.16 -- Hot surface -- Burn to finger or hand -- Keep hands safe distance from hazard 45

Figure C.17 -- High pressure fluid -- Avoid fluid escaping under pressure -- Read technical manual for proper service procedures 45

Figure C.18 -- Explosion of battery -- Read operator's manual 46

Figure C.19 -- Explosion of battery -- Jump start -- Read operator's manual 46

Figure C.20 -- Explosion hazard -- No ether -- Low temperature starting aid 47

Figure C.21 -- Severing of fingers or hand -- Keep hands safe distance from hazard 47

Figure C.22 -- Severing of foot or leg -- Keep feet and legs safe distance from hazard 48

Figure C.23 -- Severing of foot -- Keep feet safe distance from hazard 48

Figure C.24 -- Severing of head -- Read operator's manual 49

Figure C.25 -- Arm or hand entanglement in auger -- Keep hands and arms safe distance from hazard 49

Figure C.26 -- Whole body entanglement in machinery -- Stay safe distance from hazard 50

Figure C.27 -- Leg or foot entanglement or severing -- Stay safe distance from hazard 50

Figure C.28 -- Crushing of feet -- Keep feet safe distance from hazard 51

Figure C.29 -- Crushing of fingers or hands -- Keep hands safe distance from hazard 51

Figure C.30 -- Crushing of whole body -- Stay safe distance from raised loader lift arm and bucket 52

Figure C.31 -- Crushing hazard due to machine rollover -- Wear seat belt 52

Figure C.32 -- Machine tip-over or overload -- Read operator's manual 53

Figure C.33 -- Tip-over or overload of skid steer loader -- Read operator's manual 53

Figure C.34 -- Avoid being run over -- Do not ride on fender 54

Figure D.1 -- Human figure unit system 56

Figure D.2 -- Examples of human figure animation 57

Figure D.3 -- Example of pictorial using both line and bold drawing human forms 58

Figure D.4 -- Stationary, free-standing human figure 58

Figure D.5 -- Examples of pictorials using head profile 59

Figure D.6 -- Examples of pictorials showing upper torso 59

Figure D.7 -- Full palm view hand 59

Figure D.8 -- Adding hands to the human figure 60

Figure D.9 -- Examples of pictorials using a human figure with hands 60

Figure D.10 -- Examples of pictorials using hand profiles 61

Figure D.11 -- Foot development 61

Figure D.12 -- Adding feet to the human figure 62

Figure D.13 -- Example of pictorial showing the human figure with feet 62

Figure D.14 -- Examples of pictorials showing machine hazard 62

Figure D.15 -- Examples of pictorials showing individual hazard-creating components 63

Figure D.16 -- Arrow representing falling or flying objects and their direction of motion 64

Figure D.17 -- Examples of pictorials with arrows representing falling or flying objects and their direction of motion 64

Figure D.18 -- Arrow representing direction of motion of machine components 65

Figure D.19 -- Example of pictorial with arrow representing direction of motion of machine components 65

Figure D.20 -- Arrow representing direction of motion of entire machines 66

Figure D.21 -- Example of pictorial representing direction of motion of entire machines 67

Figure D.22 -- Arrow representing exertion of pressure or force 68

Figure D.23 -- Examples of pictorials with arrows representing exertion of pressure or force 69

Figure D.24 -- Arrow representing the idea of keeping a safe distance away from hazard 69

Figure D.25 -- Examples of pictorials with arrows representing keeping a safe distance from a hazard 70

Figure D.26 -- Example of pictorial using general prohibition sign to communicate prohibited action 70