ISO/TR 10064-6:2009-02 (E)

Code of inspection practice - Part 6: Bevel gear measurement methods

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Terms, definitions and symbols 2
3.1 Terms and definitions 2
3.2 Symbols 3

4 Bevel gear measurement 4
4.1 Manufacturing and purchasing considerations 4
4.2 Manufacturing documentation 5
4.3 Process control 5
4.4 Measurement methods 5
4.5 Additional considerations 6
4.6 Acceptance criteria 7

5 Measuring methods and practices 7
5.1 Guidelines for measurement of gear characteristics 7
5.2 Measuring practices 8
5.3 Measurement of pitch deviations 10
5.4 Measurement of bevel gear runout 16
5.5 Flank form measurement 18
5.6 Contact pattern checking 25
5.7 Single-flank composite inspection 30
5.8 Double-flank composite testing 30
5.9 Tooth thickness measurement 33
5.10 Manufacturing applications 36

6 Recommended datum surface tolerances 36

Bibliography 37