DIN EN 1870-12:2010-07 (E)

Safety of woodworking machines - Circular sawing machines - Part 12: Pendulum cross-cut sawing machines (includes Amendment A1:2009)

Contents

Page

Foreword 4

0 Introduction 6

1 Scope 6

2 Normative references 7

3 Terms and definitions 9

4 !!!!List of significant hazards"""" 11

5 Safety requirements and/or measures 14
5.1 Controls 14
5.1.1 Safety and reliability of control systems 14
5.1.2 Position of controls 15
5.1.3 Starting 17
5.1.4 Normal stopping 18
5.1.5 Emergency stop 19
5.1.6 Integrated feed 19
5.1.7 Mode selection 20
5.1.8 Failure of the power supply 20
5.1.9 Failure of the control circuits 20
5.2 Protection against mechanical hazards 20
5.2.1 Stability 20
5.2.2 Risk of break up during operation 21
5.2.3 Tool holder and tool design 21
5.2.4 Braking 22
5.2.5 Devices to minimise the possibility or effect of ejection 24
5.2.6 Workpiece supports and guides 24
5.2.7 Prevention of access to moving parts 26
5.2.8 Clamping devices 30
5.3 Protection against non-mechanical hazards 30
5.3.1 Fire 30
5.3.2 Noise 31
5.3.3 Emission of chips and dust 32
5.3.4 Electricity 32
5.3.5 Ergonomics and handling 32
5.3.6 Pneumatics 33
5.3.7 Hydraulics 33
5.3.8 !!!!Electromagnetic compatibility"""" 33
5.3.9 Laser 33
5.3.10 Static electricity 34
5.3.11 Errors of Fitting 34
5.3.12 Isolation 34
5.3.13 Maintenance 34

6 Information for use 35
6.1 Warning devices 35
6.2 Marking 35
6.3 Instruction handbook 36

Annex A (informative) Examples of safety related control systems with electronic components 39

Annex B (normative) Dimensional tolerances of saw spindles 43

Annex ZA (informative) !!!!Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC""""" 45

Annex ZB (informative) !!!!Relationship between this European Standard and the Essential Requirements of EU Directive 2006/42/EC""""" 46

Bibliography 47