DIN EN 1822-2:2011-01 (E)

High efficiency air filters (EPA, HEPA and ULPA) - Part 2: Aerosol production, measuring equipment, particle counting statistics

Contents

Page

Foreword 3

Introduction 4

1 Scope 5

2 Normative references 5

3 Terms and definitions 5

4 Aerosol production 5
4.1 General 5
4.2 Aerosol substances 5
4.3 Producing monodisperse aerosols 7
4.3.1 Condensation methods 7
4.3.2 Particle size classification 11
4.4 Generating polydisperse aerosols 11
4.5 Neutralisation of aerosols 11
4.6 Minimum performance parameters for aerosol generators 12
4.7 Sources of error 12
4.8 Maintenance and inspection 12

5 Measuring devices 12
5.1 Optical particle counters 12
5.1.1 Operation 12
5.1.2 Minimum performance parameters 13
5.1.3 Sources of error and limit errors 14
5.1.4 Maintenance and inspection 14
5.1.5 Calibration 14
5.2 Condensation nucleus counter 14
5.2.1 Operation 14
5.2.2 Minimum performance parameters 16
5.2.3 Sources of error and limit errors 16
5.2.4 Maintenance and inspection 17
5.2.5 Calibration 17
5.3 Differential mobility analyser 17
5.3.1 Operation 17
5.3.2 Minimum performance parameters 18
5.3.3 Sources of error and limit errors 18
5.3.4 Maintenance and inspection 19
5.3.5 Calibration 19
5.4 Particle size analysis system on the basis of differential mobility analysis 19
5.4.1 Operation 19
5.4.2 Minimum performance parameters 19
5.4.3 Sources of errors and error limits 19
5.4.4 Maintenance and inspection 19
5.4.5 Calibration 19
5.5 Dilution systems 20
5.5.1 Operation 20
5.5.2 Minimum performance parameters 20
5.5.3 Sources of error and limit errors 20

5.5.4 Maintenance and inspection 20
5.6 Differential pressure measuring equipment 20
5.7 Absolute pressure measuring equipment 21
5.8 Thermometers 21
5.9 Hygrometer 21

6 Maintenance and inspection intervals 21

7 Particle counting statistics 23

Bibliography 25