ISO 13577-4:2014-09 (E)

Industrial furnace and associated processing equipment - Safety - Part 4: Protective systems

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Design requirements for equipment in a protective system 4
4.1 General 4
4.2 Requirements for protective systems 5
4.3 Fault assessment for the hardwired section of protective systems 15
4.4 Failure of utilities 15
4.5 Reset 15

Annex A (informative) Explanation of techniques and measures for avoiding systematic faults 16

Annex B (informative) Examples of techniques for avoiding failures from external wiring 18

Annex C (informative) Examples for the determination of safety integrity level SIL using the risk graph method 22

Annex D (informative) Example of an extended risk assessment for one safety instrumented function using the IEC 61511 method 39

Annex E (informative) Sample schematic diagrams of protective system 46

Annex F (normative) Hardwiring protective systems 61

Bibliography 71