ISO 19085-6:2017-11 (E)

Woodworking machines - Safety - Part 6: Single spindle vertical moulding machines ("toupies")

Contents

Page

Foreword vi

Introduction vii

1 Scope 1

2 Normative references 2

3 Termsanddefinitions 2

4 Listofsignificanthazards 8

5 Safety requirements and measures for controls 10
5.1 Safety and reliability of control systems 10
5.2 Control devices 10
5.3 Start 11
5.4 Safe stops 11
5.4.1 General 11
5.4.2 Normal stop 11
5.4.3 Operational stop 11
5.4.4 Emergency stop 11
5.5 Braking function of tool spindles 12
5.6 Mode selection 12
5.7 Spindle speed changing 12
5.7.1 Spindle speed changing by changing belts on the pulleys 12
5.7.2 Spindle speed changing by incremental speed change motor 12
5.7.3 Infinitely variable speed by frequency inverter 12
5.7.4 Spindle speed limiting device for tenoning 12
5.7.5 Changing of the direction of spindle rotation 12
5.8 Failure of any power supply 13
5.9 Manual reset control 13
5.10 Enabling control 13
5.11 Machine moving parts speed monitoring 13
5.12 Time delay 14
5.13 Power driven adjustment of arbor, demountable power feed unit, fences and table insert 14

6 Safetyrequirementsandmeasuresforprotectionagainstmechanicalhazards 14
6.1 Stability 14
6.1.1 Stationary machines 14
6.1.2 Displaceable machines 14
6.2 Risk of break-up during operation 15
6.3 Tool holder and tool design 15
6.3.1 General 15
6.3.2 Spindle locking 17
6.3.3 Circular saw blade fixing device 18
6.3.4 Flange dimension for circular saw blades 18
6.3.5 Arbor rings 18
6.3.6 Quick tool/arbor change system 18
6.3.7 Manual adjustment of arbor height 18
6.3.8 Manual adjustment of arbor inclination 19
6.4 Braking 19

6.4.1 Braking of tool spindles 19
6.4.2 Maximum run-down time 19
6.4.3 Brake release 20
6.5 Safeguards 20
6.5.1 Fixed guards 20
6.5.2 Interlocking movable guards 20
6.5.3 Hold-to-run control 20
6.5.4 Two-hand control 20
6.5.5 Electro-sensitive protective equipment (ESPE) 20
6.5.6 Pressure-sensitive protective equipment (PSPE) 20
6.6 Prevention of access to moving parts 20
6.6.1 General 20
6.6.2 Guarding of tools 20
6.6.3 Guarding of drives 24
6.6.4 Guarding of shearing and/or crushing zones 24
6.7 Impact hazard 24
6.8 Clamping devices 24
6.9 Measures against ejection 25
6.9.1 General 25
6.9.2 Guards materials and characteristics 25
6.9.3 Anti-kickback devices 25
6.10 Work-piece supports and guides 27
6.10.1 Table 27
6.10.2 Work-piece guiding for straight work 30
6.10.3 Work-piece guiding for curved work 30
6.11 Safety appliances 31

7 Safetyrequirementsandmeasuresforprotectionagainstotherhazards 32
7.1 Fire 32
7.2 Noise 32
7.2.1 Noise reduction at the design stage 32
7.2.2 Noise emission measurement 32
7.3 Emission of chips and dust 32
7.4 Electricity 33
7.4.1 General 33
7.4.2 Displaceable machines 33
7.5 Ergonomics and handling 33
7.6 Lighting 33
7.7 Pneumatics 33
7.8 Hydraulics 33
7.9 Electromagnetic compatibility 33
7.10 Laser 34
7.11 Static electricity 34
7.12 Errors of fitting 34
7.13 Isolation 34
7.14 Maintenance 34

8 Information for use 34
8.1 Warning devices 34
8.2 Marking 34
8.2.1 General 34
8.2.2 Additional markings 34
8.3 Instruction handbook 34
8.3.1 General 34
8.3.2 Additional information 34

Annex A (informative) Performance level required 38

Annex B (normative) Test for braking function 40

Annex C (normative) Stability test for displaceable machines 41

Annex D (normative) Impact test for guards 42

Annex E (normative) Noise emission measurement for machines not in ISO 7960:1995 43

Annex F (informative) Determination of maximum spindle speeds for single piece arbors 44

Annex G (normative) Rigidity test for pressure pads, hand protectors and guiding steadies 48

Bibliography 53