DIN EN ISO 23063:2026-08 (E)

Foundry machinery - Safety requirements for high pressure die casting machines (ISO 23063:2024)

Contents

Page

Foreword ..... **v**

Introduction ..... **vi**

1 Scope **1**

2 Normative references **1**

3 Terms and definitions **3**

4 List of significant hazards **7**
4.1 General 7
4.2 Mechanical hazards 7
4.3 Electrical and control system hazards 7
4.3.1 Electrical hazards 7
4.3.2 Control system hazards 7
4.4 Thermal hazards 8
4.5 Fire hazards 8
4.6 Noise hazards 8
4.7 Hazards caused by gases, vapours, fumes and dusts 8
4.8 Hazards generated by neglecting ergonomic principles in machinery design 8
4.9 Hazards during the setting mode 9
4.10 Falls from heights 9
4.11 Hazards related to cold-chamber die casting machines 9
4.11.1 Bursting of biscuits 9
4.11.2 Injection drive area 9
4.12 Hazards related to hot-chamber die casting machines 9
4.12.1 Nozzle 9
4.12.2 Initiation of the casting process due to a fault in the control system 9
4.13 Hazards due to hydraulics and pneumatics 9

5 Safety requirements and/or protective measures **10**
5.1 General 10
5.2 Mechanical 10
5.2.1 General 10
5.2.2 Guards and protective devices for the die area 10
5.2.3 Access to the die closing mechanism area 12
5.2.4 Additional requirements for movable guards and access doors 12
5.2.5 Die casting units 13
5.3 Electric equipment and control systems 14
5.3.1 Electric equipment 14
5.3.2 Safety related parts of the control system: General 14
5.3.3 Emergency stop functions 14
5.3.4 Safety related control system of the dangerous movements of the die 14
5.3.5 Control of ancillary equipment 15
5.4 Measures against thermal hazards 16
5.4.1 Spurting of molten metal 16
5.4.2 Contact with hot surfaces 16
5.5 Hydraulics, pneumatics and combustible fluids 16
5.5.1 Hydraulics, pneumatics 16
5.5.2 Pressure fluids 16
5.5.3 Spray systems for release agents 16
5.6 Noise 17

5.6.1 Noise reduction as a safety requirement 17
5.6.2 Noise emission measurement and declaration on die casting machines 17
5.6.3 Noise test code 17
5.7 Gases, vapours, fumes and dusts 19
5.8 Ergonomic aspects 19
5.9 Protective measures when setting-up of die casting machines, inserting and removing appliances, tie bar pulling devices and other ancillary equipment 19
5.9.1 Setting-up without protective devices for the die area 19
5.9.2 Movement of core pullers and ejectors 20
5.9.3 Movement of tie bars 20
5.9.4 Movement of the plunger of cold-chamber machines 20
5.10 Elevated working places 20
5.11 Additional protective measures for cold-chamber die casting machines 21
5.11.1 Bursting and removal of biscuit 21
5.11.2 Guards and protective devices for the injection area 21
5.12 Additional protective measures for hot-chamber die casting machines 21
5.12.1 Metal splashing 21
5.12.2 Movement of the injection piston 21

6 Verification of the safety requirements and/or protective measures 22

7 Information for use 23
7.1 General 23
7.2 Warning devices and safety signs 23
7.3 Accompanying documents 23
7.3.1 Instruction handbook 23
7.4 Marking 25

Annex A (informative) **Examples 27**

Annex B (normative) **Requirements for the European Union and associated countries 40**

Annex C (normative) **Requirements for China (noise test code) 41**

Bibliography 42