ISO 16890-2:2022-07 (E)

Air filters for general ventilation - Part 2: Measurement of fractional efficiency and air flow resistance

Contents

Page

Foreword vi

Introduction viii

1 Scope 1

2 Normative references 1

3 Terms and definitions 1
3.1 Air flow and resistance 2
3.2 Test device 2
3.3 Aerosol 2
3.4 Particle counter 3
3.5 Efficiency 3
3.6 Other terms 4

4 Symbols and abbreviated terms 4
4.1 Symbols 4
4.2 Abbreviated terms 6

5 General test requirements 6
5.1 Test device requirements 6
5.2 Test device installation 6
5.3 Test rig requirements 7

6 Test materials 7
6.1 Liquid phase aerosol 7
6.1.1 DiEthylHexylSebacate (DEHS) test aerosol 7
6.1.2 DEHS properties 7
6.1.3 Liquid phase aerosol generation 7
6.2 Solid phase aerosol 8
6.2.1 Potassium chloride (KCl) test aerosol 8
6.2.2 KCl properties 8
6.2.3 Solid phase aerosol generation 9
6.3 Reference aerosols 10
6.3.1 Reference aerosol for 0,3 µm to 1,0 µm 10
6.3.2 Reference aerosol for 1,0 µm to 10,0 µm 10
6.4 Aerosol loading 10

7 Test equipment 11
7.1 Test rig 11
7.1.1 Dimensions 11
7.1.2 Construction materials 11
7.1.3 Test rig shape 12
7.1.4 Test rig air supply 12
7.1.5 Test rig isolation 12
7.1.6 D/S mixing orifice 12
7.1.7 Aerosol sampling 13
7.1.8 Test rig air flow rate measurement 15
7.1.9 Resistance to air flow measurement 15
7.1.10 Test devices not measuring 610 mm × 610 mm (24.0 inches × 24.0 inches) 16

7.1.11 Dust injection testing 16
7.2 Aerosol particle counter 17
7.2.1 General 17
7.2.2 OPC sampled size range 17
7.2.3 OPC particle size ranges 17
7.2.4 Sizing resolution 18
7.2.5 Calibration 18
7.2.6 Air flow rate 18
7.2.7 Zero counting 18

7.2.8 Dual OPC(s) 18
7.3 Temperature, relative humidity 18

8 Qualification of test rig and apparatus 19
8.1 Schedule of qualification testing requirements 19
8.1.1 General 19
8.1.2 Qualification testing 19
8.1.3 Qualification documentation 19
8.2 Qualification testing 20
8.2.1 Test rig -- Pressure system testing 20
8.2.2 OPC -- Air flow rate stability test 21
8.2.3 OPC -- Zero test 21
8.2.4 OPC -- Sizing accuracy 21
8.2.5 OPC -- Overload test 22
8.2.6 Aerosol generator -- Response time 22
8.2.7 Aerosol generator -- Neutralizer 23
8.2.8 Test rig -- Air leakage test 24
8.2.9 Test rig -- Air velocity uniformity 24
8.2.10 Test rig -- Aerosol uniformity 25
8.2.11 Test rig -- Downstream mixing 26
8.2.12 Test rig -- Empty test device section pressure 28
8.2.13 Test rig -- 100 % efficiency test and purge time 28
8.2.14 Test rig -- Correlation ratio 29
8.3 Maintenance 29
8.3.1 General 29
8.3.2 Test rig -- Background counts 30
8.3.3 Test rig -- Reference filter test 30
8.3.4 Test rig -- Pressure reference test 31
8.3.5 Test rig -- Final filter resistance 32

9 Test methods 32
9.1 Air flow rate 32
9.2 Measurement of resistance to air flow 32
9.3 Measurement of fractional efficiency 32
9.3.1 Aerosol sampling protocol 32
9.3.2 Background sampling 32
9.3.3 Testing sequence for a single OPC 33
9.3.4 Testing sequence for dual OPC 37

10 Data reduction and calculations 38
10.1 Correlation ratio 38
10.1.1 Correlation ratio general 38
10.1.2 Correlation ratio data reduction 39
10.2 Penetration and fractional efficiency 40
10.2.1 Penetration and fractional efficiency general 40
10.2.2 Penetration data reduction 41
10.3 Data quality requirements 43
10.3.1 Correlation background counts 43
10.3.2 Efficiency background counts 43
10.3.3 Correlation ratio 43
10.3.4 Penetration 44
10.4 Fractional efficiency calculation 45

11 Reporting results 45
11.1 General 45
11.2 Required reporting elements 45
11.2.1 Report general 45
11.2.2 Report values 45
11.2.3 Report summary 46
11.2.4 Report details 47

Annex A (informative) Example 50

Annex B (informative) Resistance to air flow calculation 57

Bibliography 59