ISO 23742:2024-06 (E)

Test method for the evaluation of permeability and filtration efficiency distribution of bag filter medium

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Determination of sampling 2
4.1 General 2
4.2 Collection position, size and shape of representative sample sheets 2
4.3 Number of representative sample sheets 2

5 Preparation of specimen strips 3
5.1 General 3
5.2 Standard atmosphere for conditioning and testing 3
5.3 Conditioning of specimen strips 3
5.4 Size of specimen strips 3

6 Measurement method - Thickness 4
6.1 General 4
6.2 Apparatus 4
6.2.1 Thickness tester 4
6.2.2 Thickness gauge 4
6.3 Procedure 4

7 Measurement method - Area mass 4
7.1 General 4
7.2 Apparatus 4
7.2.1 Precision balance 4
7.2.2 Calibrated rule 5
7.3 Procedure 5

8 Measurement method - Gas permeability 5
8.1 General 5
8.2 Apparatus 5
8.2.1 Circular specimen holder 5
8.2.2 Clamping device 5
8.2.3 Guard ring device 5
8.2.4 Pressure gauge or manometer 5
8.2.5 Blower, fan or pump 5
8.2.6 Flowmeter, volumetric counter or measuring aperture 5
8.3 Procedure 5

9 Measurement method - Filtration efficiency (option) 6

10 Order of measurement sequence 6

11 Expression of distribution of each measurement item 6

12 Test report 7

Annex A (normative) Sampling survey theory based on normal distribution 8

Annex B (informative) Analysis example of measurement results 9

Annex C (informative) Example of relationship between exerting pressure and thickness distribution 13

Annex D (informative) Example of a test report 14

Annex E (informative) Example of a test report with measurement results 16

Bibliography 18