ISO 23063:2024-11 (E)

Foundry machinery - Safety requirements for high pressure die casting machines

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 3

4 Listofsignificanthazards 7
4.1 General 7
4.2 Mechanical hazards 7
4.3 Electrical and control system hazards 7
4.3.1 Electrical hazards 7
4.3.2 Control system hazards 7
4.4 Thermal hazards 8
4.5 Fire hazards 8
4.6 Noise hazards 8
4.7 Hazards caused by gases, vapours, fumes and dusts 8
4.8 Hazards generated by neglecting ergonomic principles in machinery design 8
4.9 Hazards during the setting mode 9
4.10 Falls from heights 9
4.11 Hazards related to cold-chamber die casting machines 9
4.11.1 Bursting of biscuits 9
4.11.2 Injection drive area 9
4.12 Hazards related to hot-chamber die casting machines 9
4.12.1 Nozzle 9
4.12.2 Initiation of the casting process due to a fault in the control system 9
4.13 Hazards due to hydraulics and pneumatics 9

5 Safety requirements and/or protective measures 10
5.1 General 10
5.2 Mechanical 10
5.2.1 General 10
5.2.2 Guards and protective devices for the die area 10
5.2.3 Access to the die closing mechanism area 12
5.2.4 Additional requirements for movable guards and access doors 12
5.2.5 Die casting units 13
5.3 Electric equipment and control systems 14
5.3.1 Electric equipment 14
5.3.2 Safety related parts of the control system: General 14
5.3.3 Emergency stop functions 14
5.3.4 Safety related control system of the dangerous movements of the die 14
5.3.5 Control of ancillary equipment 15
5.4 Measures against thermal hazards 16
5.4.1 Spurting of molten metal 16
5.4.2 Contact with hot surfaces 16
5.5 Hydraulics, pneumatics and combustible fluids 16
5.5.1 Hydraulics, pneumatics 16
5.5.2 Pressure fluids 16
5.5.3 Spray systems for release agents 16

5.6 Noise ... 17
5.6.1 Noise reduction as a safety requirement ... 17
5.6.2 Noise emission measurement and declaration on die casting machines ... 17
5.6.3 Noise test code ... 17
5.7 Gases, vapours, fumes and dusts ... 19
5.8 Ergonomic aspects ... 19

5.9 Protective measures when setting-up of die casting machines, inserting and removing appliances, tie bar pulling devices and other ancillary equipment ... 19
5.9.1 Setting-up without protective devices for the die area ... 19
5.9.2 Movement of core pullers and ejectors ... 20
5.9.3 Movement of tie bars ... 20
5.9.4 Movement of the plunger of cold-chamber machines ... 20
5.10 Elevated working places ... 20
5.11 Additional protective measures for cold-chamber die casting machines ... 21
5.11.1 Bursting and removal of biscuit ... 21
5.11.2 Guards and protective devices for the injection area ... 21
5.12 Additional protective measures for hot-chamber die casting machines ... 21
5.12.1 Metal splashing ... 21
5.12.2 Movement of the injection piston ... 21

6 Verificationofthesafetyrequirementsand/orprotectivemeasures ... 22

7 Information for use ... 23
7.1 General ... 23
7.2 Warning devices and safety signs ... 23
7.3 Accompanying documents ... 23
7.3.1 Instruction handbook ... 23
7.4 Marking ... 25

Annex A (informative) Examples ... 27

Annex B (normative) Requirements for the European Union and associated countries ... 40

Annex C (normative) Requirements for China (noise test code) ... 41

Bibliography ... 42